

AIP Vanuatu

AIRAC**AIP SUPPLEMENT****Effective
23 MAY 19****Effective at: 1905221300 UTC*****Initial issue***

CONTENTS

2019

1/19	Port Vila AD (NVVV) — ALS RWY 11 U/S	1
2/19	Santo/Pekoa AD (NVSS) — SANTO DME 'SON' 114.5 MHz Unmonitored	1
3/19	AIP Publications Status Checklist	1

1/19

Port Vila AD (NVVV) — ALS RWY 11 U/S

Effective: 23 MAY 19

The Port Villa AD AL5 (Circling Guidance Lights) for RWY 11 are unserviceable UFN.

2/19

Santo/Pekoa AD (NVSS) — SANTO DME 'SON' 114.5 MHz Unmonitored

Effective: 23 MAY 19

Pilots are advised that the Santo DME 'SON' frequency 114.5 MHz is operational but caution is advised due to it being unmonitored.

3/19

AIP Publications Status Checklist

Effective: 23 MAY 19

The purpose of this AIP Supplement is to advise the current status of AIP Vanuatu products and associated charting.

AIP Vanuatu 23 MAY 19

AIP Supplement 23 MAY 19

Supplements Cancelled

Nil